Repair instruction

Description: SC250/C260 Waste-holding tank mechanism

Part Number: 50727-06

Look for Service Centres, Point of Sale addresses and other information on:
www.thetford.eu

Version:	V2
Date:	August 2011
Tools required:	

In case you are operating on a C250 and changing your Holding Tank, The Holding tank Mechanism, or the plate only of the Holding tank mechanism, it is strongly recommended to also change the bowl retainer bracket to avoid Leakage !

A

While looking down on the top of the tank you will notice the sliding cover. Also on the disc there is an arrow which is pointing to a solid dot on the main body of the toilet.



B

Remove the sliding cover and re-insert from the opposite end.



C

Using the sliding cover as a lever rotate the complete mechanism anti clockwise until the arrow points to the second dot.



D

The complete disc and mechanism can now be removed, reverse the process to re-attach the new mechanism.

